

Here are the pictures on how to ground the LV and HV modules in a HE RBX. Strap under the box goes to a bolt in absorber.





